

General Environmental Incident Summary

Incident: 3561 **Date/Time Notice:** 11/20/2014 1600 **DEM Incident No:**
Responsible Party: Minnesota Power
Date Incident: 11/20/2014 **Time Incident:** 1015 **Duration:**
County: Oliver **Twp:** 141 **Rng:** 85 **Sec:** 29 **Qtr:**
Lat: 47.08592 **Long:** -101.39190 **Method:** Interpolation from map
Location Description: 5198 30th Street , New Salem
Exit 120 from hWy 94, go north 8 miles and east 2 miles
Submitted By: Greg Prom **Affiliation:** Envioronmental Compl Spec
Address: 30 West Superior
City: Duluth **State:** MN **Zip:** 55802

Received By:

Contact Person: Todd Simmons
5198 30th Street
New Salem, ND

Distance Nearest Occupied Building: 200 Feet **Release Contained:** Yes

Type of Incident: diesel spill from refueling operation

Description of Released Contaminant: diesel fuel

Volume Spilled: 5.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Overfill durign refueling operations

Risk Evaluation:

The spill impacted soil but was immediately cleaned up and the ground is frozen so the environmental risk and health hazard is minimal.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Since the ground is frozen and the spill was cleaned up and containerized immediately the enviornmental risk has been negated.

Action Taken or Planned:

The fuel was immediately absorbed with absorbent material and cleaned up residual with by shovel and placed in 55-gallon drums for disposal

Wastes Disposal Location: Clean Harbors will transport and dispose of the waste at the industrial landfill in Sawyer, ND.

Agencies Involved:

Updates

Date: 11/21/2014 ***Status:*** Reviewed - No Action Required

Author: Espe, Brady

Updated Volume:

Notes:

According to the incident summary, this spill was immediately contained, and cleanup was properly handled. No followup is necessary.